Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC.

Well Name: COTTONWOOD 2-35H

Field Name: COTTONWOOD Well File #: 17850

Date Incident: 7/8/2016 Time Incident: 15:00 Facility ID Number:

County: MOUNTRAIL Twp: 157 Rna: 92 Sec: 35 Qtr: SE SE

Location Description:

Submitted By: Matt Richards Received By:

Contact Person: Matt Richards

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
30 Gallons 30 Gallons 30 gallons

Brine Other

Oil

Description of Other Released Contaminant:

Inspected: Written Report Received: 8/3/2016 Clean Up Concluded: 7/8/2016

Risk Evaluation:

None

Areal Extent:

The light spray covered an 85' x 33' area off location

Friday, February 10, 2017 Page 1 of 2

Potential Environmental Impacts:

None

Action Taken or Planned:

After speaking with the farmer, we used a mower to remove contaminated grass and used a skidsteer to remediate soil on site.

Wastes Disposal Location: Remediation will occur onsite

Agencies Involved:

Updates

Date: 7/11/2016 Status: Inspection Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 7/11/2016, at 1:22 p.m. Release sprayed off location to the north. Area of impact is native grasses. Area has been cut nearly to bare ground in an area approximately 150 X 100 feet. No remaining impacts seen on soil or vegetation at this time. Follow up to check on vegetation growth.

Date: 7/11/2016 Status: Reviewed - Follow-up Required Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, there was a mist of product off the well pad. Further follow-up needed.